

DAFTAR GAMBAR

	Halamaan
Gambar 2.1 Pilar TPM.....	II-16
Gambar 2.2 <i>Six Big Losses</i>	II-28
Gambar 2.3 <i>Checksheet</i>	II-37
Gambar 2.4 Diagram Pareto	II-38
Gambar 2.5 <i>Fishbone Diagram</i>	II-40
Gambar 2.6 Histogram	II-41
Gambar 2.7 <i>Scatter Diagram</i>	II-42
Gambar 2.8 <i>Control Chart</i>	II-44
Gambar 3.1 <i>Flowchart</i> Tahap Penelitian	III-6
Gambar 4.1 PT Megah Megalon <i>Industries</i>	IV-2
Gambar 4.2 Layout Perusahaan	IV-5
Gambar 4.3 Produk yang dihasilkan.....	IV-6
Gambar 4.4 Bahan Baku Serat.....	IV-9
Gambar 4.5 <i>Bale Opener</i>	IV-11
Gambar 4.6 <i>Breaker 01</i>	IV-12
Gambar 4.7 <i>Metal Detector</i>	IV-12
Gambar 4.8 <i>Mixing</i>	IV-13
Gambar 4.9 <i>Breaker 02</i>	IV-14
Gambar 4.10 <i>Carding A</i>	IV-14
Gambar 4.11 <i>Cross Lapper</i>	IV-15
Gambar 4.12 <i>Carding B</i>	IV-16
Gambar 4.13 <i>Embossed</i>	IV-16
Gambar 4.14 <i>Oven</i>	IV-17
Gambar 4.15 <i>Roll Heating</i>	IV-18
Gambar 4.16 <i>Roll Finishing</i>	IV-18

Gambar 1.17 <i>Roll Cooling</i>	IV-19
Gambar 4.18 <i>Center Winding</i>	IV-19
Gambar 4.19 Nilai Standar OEE.....	IV-28
Gambar 4.20 <i>Availability Ratio</i>	IV-30
Gambar 4.21 <i>Performance Ratio</i>	IV-33
Gambar 4.22 <i>Quality Ratio</i>	IV-35
Gambar 4.23 <i>Overall Equipment Effectivness</i>	IV-37
Gambar 4.24 <i>Pareto Chart Defect Lini 2</i>	IV-40
Gambar 4.25 <i>Fishbone Defect Kotor Hitam Pada Lini 2</i>	IV-42
Gambar 4.26 <i>Pareto Chart Breakdown Lini 3</i>	IV-51
Gambar 4.27 <i>Fishbone Breakdown Carding A Pada Lini 3</i>	IV-53