

DAFTAR GAMBAR

Gb 2.1 Model Perbaikan Kualitas	II – 9
Gb 2.2 Tiga Strategi Six Sigma	II – 18
Gb 2.3 konsep Six Sigma Motorola Dengan Pergeseran 1.5 Sigma	II – 20
Gb 2.4 Hierarki Personil Six Sigma.....	II – 32
Gb 2.5 Diagram Pareto	II – 37
Gb 2.6 SIPOC Diagram	II – 39
Gb 2.7 Tindakan Untuk Meningkatkan Proses	II – 52
Gb 2.8 Fishbone Diagram	II – 57
Gb 2.9 FMEA	II – 61
Gb 3.1 Tahapan Penelitian	III – 1
Gb 4.1 Uncoiler.....	IV – 13
Gb 4.2 Lubricator.....	IV – 14
Gb 4.3 Cupper.....	IV – 15
Gb 4.4 Body Maker.....	IV – 16
Gb 4.5 Trimmer	IV – 16
Gb 4.6 Washer	IV – 18
Gb 4.7 Pal/Depal.....	IV – 19
Gb 4.8 Decorator.....	IV – 21
Gb 4.9 LSM	IV – 22
Gb 4.10 IBO.....	IV – 23
Gb 4.11 Necker-necker	IV – 24
Gb 4.12 SNF	IV – 24
Gb 4.13 Pin Hole Detector.....	IV – 25
Gb 4.14 Visual Check	IV – 26
Gb 4.15 Palletizer.....	IV – 26

Gb 4.16 Strapper	IV – 27
Gb 4.17 Wrapper.....	IV – 27
Gb 4.18 Visual Check 1	IV – 28
Gb 4.19 Visual Check 2	IV – 29
Gb 4.20 M.E Check	IV – 29
Gb 4.21 Diagram Pareto Jumlah Defect Can Body 250ml	IV – 35
Gb 4.22 Peta Kendali P Defect M.E High 2008-2009	IV – 48
Gb 4.23 Peta Kendali P Revisi Defect M.E High 2008-2009	IV – 49
Gb 4.24 Fishbone Diagram CTQ M.E High	IV – 54
Gb 4.25 Fishbone Diagram Kegagalan LSM	IV – 61
Gb 4.26 Struktur Organisasi Pada Lini Produksi	IV – 70
Gb 4.27 Usulan Struktur Team Six Sigma.....	IV – 72
Gb 4.28 Prioritas Penanganan Perbaikan	IV – 78
Gb 4.29 SOP Maintenance LSM.....	IV – 83
Gb 4.30 Run Chart Tingkat Defect	IV – 84
Gb 4.31 Form Usulan Pencapaian Target	IV – 85
Gb.4.32 Form Usulan Report Maintenance	IV – 87
Gb 5.1 Diagram Pareto	V – 2
Gb 5.2 Perbandingan Level Sigma&DPMO 2008-2009.....	V – 5