

DAFTAR ISI

HALAMAN PENGESAHAN.....	i
HALAMAN PERNYATAAN KEASLIAN	ii
HALAMAN PERSETUJUAN PUBLIKASI ILMIAH	iii
ABSTRAK	iv
KATA PENGANTAR	vi
DAFTAR ISI.....	vii
DAFTAR GAMBAR	x
DAFTAR TABEL.....	xi
DAFTAR LAMPIRAN.....	xii
BAB I PENDAHULUAN	
1.1 Latar Belakang	1
1.2 Rumusan Masalah	2
1.3 Batasan Masalah.....	2
1.4 Tujuan Penelitian	2
1.5 Manfaat Penulisan.....	2
1.6 Sistematika Penulisan.....	3
BAB II LANDASAN TEORI	
2.1 Maintenance	5
2.1.1 Pengertian Mintenance.....	5
2.1.2 Fungsi Mintenance	5
2.1.3 Jenis-jenis Maintenance	6
2.1.4 Tujuan Mintenance.....	7
2.1.5 Tugas dan Pelaksanaan Kegiatan Maintenance	7
2.2 TPM (<i>Total Productive Maintenance</i>)	8
2.2.1 Elemen dasar TPM (<i>Total Productive Maintenance</i>)	8
2.2.2 Manfaat TPM (<i>Total Productive Maintenance</i>).....	9
2.2.3 Pilar TPM (<i>Total Productive Maintenance</i>)	9
2.3 OEE (<i>Overall Equipment Effectiveness</i>).....	10
2.3.1 Availability.....	11
2.3.2 Performance Rate	11
2.3.3 Quality Rate	12
2.4 <i>Six Big Losses</i> (Enam Kerugian Besar).....	12
2.4.1 <i>Breakdown Losses</i>	12
2.4.2 <i>Set up and adjustment losses</i>	12
2.4.3 <i>Idling and minor stoppage losses</i>	13
2.4.4 <i>Reduced Speed losses</i>	13
2.4.5 <i>Quality Defect and Rework</i>	13
2.4.6 <i>Yield/ scrap Losses</i>	13
2.5 Alat Pemecahan Masalah	13

2.5.1	<i>Cause Effect/Fishbone Diagram</i> (Diagram Sebab Akibat/Diagram Tulang Ikan)	14
2.5.2	<i>Pareto Diagram</i> (Diagram Pareto).....	16
2.6	<i>CTQ (Critical To Quality)</i>	17
2.6.1	Pengertian <i>CTQ (Critical To Quality)</i>	17
2.6.2	Langkah-langkah membuat <i>CTQ</i>	17
2.7	<i>FMEA (Failure Mode and Effect Analysis)</i>	18
2.7.1	Tipe <i>FMEA (Failure Mode and Effect Analysis)</i>	19
2.7.2	Tujuan Implementasi <i>FMEA (Failure Mode and Effect Analysis)</i>	20
2.7.3	Keuntungan Implementasi <i>FMEA (Failure Mode and Effect Analysis)</i>	20
2.7.4	Variabel <i>FMEA (Failure Mode and Effect Analysis)</i>	20
BAB III METODELOGI PENELITIAN		
3.1	Lokasi dan Waktu Penelitian	24
3.2	Jenis Penelitian dan Sumber Data Penelitian	24
3.3	Objek Penelitian	24
3.4	Tahapan Penelitian	25
3.4.1	Mulai	25
3.4.2	Mengidentifikasi dan merumuskan masalah	26
3.4.3	Studi Literatur dan lapangan	26
3.4.4	Menetapkan tujuan	26
3.4.5	Mempelajari proses produksi dan mesin yang ada di dalam.....	26
3.4.6	Pengumpulan data	26
3.4.7	Pengolahan dan analisis data.....	27
3.4.8	Perencanaan solusi perbaikan	27
3.4.9	Kesimpulan dan saran	28
BAB IV PENGUMPULAN DAN PENGOLAHAN DATA		
4.1	Pengumpulan Data	29
4.1.1	Gambaran Umum Perusahaan.....	29
4.1.2	Tugas dan Wewenang	29
4.1.3	Profil Perusahaan	30
4.1.4	Objek Penelitian	30
4.2	Pengolahan Data.....	34
4.2.1	Analisa Data Jomar 65	34
4.2.2	Analisa Data Winon Auto Print	39
4.2.3	Rekapitulasi Analisa Pengolahan Data OEE.....	44
4.2.4	Analisis Losses.....	44

BAB V ANALISA HASIL

5.1 Identifikasi availability losses	48
5.2 Analisis faktor penyebab.....	49
5.3 Analisis CTQ.....	55
5.4 Analisis FMEA.....	57

BAB VI KESIMPULAN DAN SARAN

6.1 Kesimpulan	66
6.2 Saran.....	67

DAFTAR PUSTAKA

LAMPIRAN



DAFTAR GAMBAR

Gambar 2.1 Pilar TPM	8
Gambar 2.2 <i>Fishbone Diagram</i>	15
Gambar 2.3 Diagram Pareto.....	16
Gambar 2.4 Mtrix CTQ.....	17
Gambar 3.1 <i>Flowchart</i> penelitian	24
Gambar 4.1 Mesin Mixer	30
Gambar 4.2 Metal Separator	30
Gambar 4.3 Mesin Jomar 65	31
Gambar 4.4 Mesin Winon Auto Print	31
Gambar 4.5 Biji Plastik HDPE Marlex	32
Gambar 4.6 Masterbach warna putih	32
Gambar 4.7 Karton Box	33
Gambar 4.8 Grafik OEE dari Jomar 65.....	35
Gambar 4.9 Grafik <i>Availability ratio</i> dari Jomar 65	36
Gambar 4.10 Grafik <i>Performance Rate</i> mesin Jomar 65	37
Gambar 4.11 Grafik <i>Quality Rate</i> mesin Jomar 65.....	38
Gambar 4.12 Grafik OEE mesin Winon Auto Print	39
Gambar 4.13 Grafik <i>Availability ratio</i> mesin Winon Auto Print.....	40
Gambar 4.14 Grafik <i>Performance Rate</i> mesin Winon Auto Print	41
Gambar 4.15 Grafik <i>Quality Rate</i> mesin Winon Auto Print.....	42
Gambar 5.1 Diagram Pareto Breakdown Losses	46
Gambar 5.2 Diagram Pareto set up and adjustment time losses	47
Gambar 5.3 Flowchart Mesin Insto.....	49
Gambar 5.4 <i>Fishbone Diagram Breakdown Losses Mechanical</i>	50
Gambar 5.5 <i>Fishbone diagram Set Up And Adjustment Losses Mechanical</i>	52

DAFTAR TABEL

Tabel 2.1 Standar dunia OEE.....	10
Tabel 2.2 Ranking <i>severity</i> of Ford Motor Company	20
Tabel 2.3 Ranking <i>Occurrence</i> of Ford Motor Company	21
Tabel 2.4 Ranking <i>Detection</i> of Ford Motor Company	22
Tabel 4.1 Profil Perusahaan	29
Tabel 4.2 Data Mesin Jomar 65	34
Tabel 4.3 Data OEE Mesin Jomar 65.....	34
Tabel 4.4 Data Availability mesin Jomar 65.....	35
Tabel 4.5 Data Performance Rate mesin Jomar 65	36
Tabel 4.6 Data Quality Rate mesin Jomar 65.....	37
Tabel 4.7 Data Mesin Winon Auto Print	38
Tabel 4.8 Data OEE Mesin Winon Auto Print.....	39
Tabel 4.9 Data Availability mesin Winon Auto Print.....	40
Tabel 4.10 Data Performance rate mesin Winon Auto Print	41
Tabel 4.11 Data Quality Rate mesin Winon Auto Print.....	42
Tabel 4.12 Rekapitulasi Analisa Pengolahan Data OEE	43
Tabel 4.13 Data Breakdown Losses mesin Jomar 65	44
Tabel 4.14 Data Set up and adjustment losses mesin Jomar 65.....	45
Tabel 5.1 Matrix CTQ <i>breakdown losses</i>	54
Tabel 5.2 Matrix CTQ <i>set up and adjustment losses</i>	55
Tabel 5.3 <i>Failure Mode and Effect Analysis</i>	56

DAFTAR LAMPIRAN

Lampiran 1 Data *Production Efficiency* PT. XYZ, Tbk

Lampiran 2 Data *Availabiliy ratio* mesin Jomar 65 dan Winon Auto Print

