### Universi Esa

## DAFTAR ISI

HALAMAN JUDUL ······i
HALAMAN PERNYATAAN KEASLIAN ······ii
HALAMAN PENGESAHAN ······iii
KATA PENGANTAR ······iv
ABSTRAK ·······vi
DAFTAR ISI ······vii
DAFTAR GAMBAR······vii
BAB I1
1.1 Latar Belakang1
1.2 Rumusan Masalah2
1.3 Tujuan Penelitian2
1.4 Batasan Masalah2
1.5 Sistematika Penulisan3
BAB II5
2.1 Perawatan Mesin ·····5
2.2 Tujuan Perawatan Mesin ······6
2.3 Penyempurnaan Perawatan Mesin ······7
2.4 Mesin C2000 ····· 8
2.5 Overall Equipment Effectiveness (OEE)9
2.5.1 Ketersediaan Mesin (Availability) ······ 10
2.5.2 Kinerja Mesin ( <i>Performance</i> )
2.5.3 Kualitas Output ( <i>Quality</i> ) ······ 12
2.6 Analisis Produktifitas <i>Six Big Losses</i>

#### Universit

2.7 Diagram Sebab Akibat ·····	14
2.8 Histogram ·····	17
2.9 Metode 5W + 1H ·····	17
BAB III ·····	19
3.1 Pendekatan Penelitian	19
3.2 Tempat dan Waktu Penelitian	19
3.3 Metode Penelitian ·····	19
3.4 Obyek Penelitian` ·····	19
3.5 Tahapan Penelitian ·····	20
BAB IV	21
4.1 Pengumpulan Data ······	21
4.2 Pengolahan Data	21
4.2.1 Perhitungan Ketersediaan Mesin ( <i>Availability</i> ) ······	21
4.2.2 Perhitungan Kinerja Mesin ( <i>Performance</i> ) ······	23
4.2.3 Perhitungan Kualitas Output (Quality) ······	24
4.2.4 Perhitungan OEE ·····	26
4.2.5 Perhitungan Six Big Losses	27
BAB V	29
5.1 Analisis Ketersediaan (Availability)	29
5.2 Analisis Kinerja Mesin (Performance)	29
5.3 Analisis Kualitas Output (Quality)	29
5.4 Analisis OEE	30
5.5 Analisis Mesin C200	31
5.6 Analisis Penyebab Kerusakan Mesin	33
5.7 Usulan Perbaikan ······	34

AB VI 3	7
5.1 Kesimpulan ····· 3	7
5.1 Saran ······ 3	8

#### DAFTAR PUSTAKA





### DAFTAR GAMBAR

Gambar 2.1 Mesin C2000 ······	3
Gambar 2.2 Diagram Sebab Akibat	5
Gambar 5.1 Diagram Mesin C2000 ······ 30	)
Gambar 5.2 Persentase Rata-rata Six Big Losses	1
Gambar 5.3 Diagram Sebab Akibat	3

Esa Unggul

### DAFTAR TABEL

Tabel 4.1 Data Availability Mesin C200022
Tabel 4.2 Data Performance Mesin C2000 23
Tabel 4.3 Data Quality Mesin C2000 25
Tabel 4.4 Data OEE Mesin C2000      26
Tabel 4.5 Data Six Big Losses Mesin C2000······ 27
Tabel 5.1 Analisa Sebab Akibat ····· 34
Tabel 5.2 Usulan Perbaikan dengan metode 5W + 1H ····· 34

# Esa Unggul