




OSRAM

STANDARD WORK

Coating-Flare-Stem Operator

Line B1-B2

STANDARD WORK						
Coating-Flare-Stem Operator						
Line B1-B2						
Job Area	Job Description			Number Of Operator		
	Shift 1	Shift 2	Shift 3	Sum	Remarks	
Coating, Flare, Stem	Pembuatan stamp (change over)	1	1	1	Working for Coat, Flare, Stamp & Stem Machine	
	Loading glass tube					
	Shorter flare					
	Loading LIW					
	Memisahkan dan menyiapkan kotak BS Coating					
	Loading cut flare ke mc. Stem					
	Loading exh.tube ke mc. Stem					
	Check dan mengoles tinta stamp.					
	Supply bulb dan buang karton					
	Merapikan, menempatkan karton bekas flare tube					
	House Keeping					
	Manual wire bengkok					
	Loading bulb ke coating mc					
	Control conveyor coat to baking					
	Penempatan material bulb dimeja					
	- Merapikan & menempatkan karton bekas bulb					
	Memindah mat. exh tube to mc stem					
	Memindah mat glass tube flare ke tempat flare					
	Memindah palet bulb kosong ke area coat					
	Memindah palet bulb kosong ke area palet					



Remark:


- A. Tempat Karton Bekas
 - B. Tempat Powder Coating
 - C. Mixer Tabung Coating
 - D. Palet tempat Material Bulb
 - E. Getter
 - F. Zirconium
 - G. Roll mixer getter
 - H. Lemari mounting
 - I. Material Karton dan Do
 - J. Palet Packing Lamp
 - K. Shrinkpack
 - L. Manual Solder



OSRAM

STANDARD WORK
Mounting Operator
Line B1-B2

Job Area	Job Description	Number Of Operator			Remarks
		Shift 1	Shift 2	Shift 3	
Mounting	Loading mounting - Pengontrolan bulb dr baking	1	1	1	3
	Loading stem ke mc. Mounting				Working for Mounting Machine
	Pengontrolan vibrator flare				
	Check rel stem ke mc mounting				
	Loading filament & sorter				
	Manual mounting				
	Loading mounting - Pengontrolan bulb dr baking				
	Loading stem ke mc. Mounting				
	Pengontrolan vibrator flare				
	Check rel stem ke mc mounting				



- Remark:


- A. Tempat Karton Bekas
 - B. Tempat Powder Coating
 - C. Mixer Tabung Coating
 - D. Palett tempat Material Bulu
 - E. Getter
 - F. Zincorium
 - G. Roll river setter

- H. Leman mounting
 - I. Material Karton dan Dose
 - J. Palet Packing Lamp
 - K. Shrinkage
 - L. Manual Solder



OSRAM

STANDARD WORK
Sealing Operator
Line B1-B2




Remark:

- A. Tempat Karton Bekas
 - B. Tempat Powder Coating
 - C. Mixer Tabung Coating
 - D. Palet tempat Material Bub
 - E. Getter
 - F. Zirconium
 - G. Roll mixer getter
 - H. Lemari mounting
 - I. Material Karton dan Dose
 - J. Palet Packing Lamp
 - K. Shrinkpack
 - L. Manual Solder



OSRAM

STANDARD WORK
Basing Operator
Line B1-B2



Remark:


- A. Tempat Karton Bekas
 - B. Tempat Powder Coating
 - C. Mixer Tabung Coating
 - D. Palet tempat Material Bulu
 - E. Getter
 - F. Zirconium
 - G. Rollmixer getter
 - H. Lemari mounting
 - I. Material Karton dan Dose
 - J. Palet Packing Lamp
 - K. Shrinkpack
 - L. Manual Solder



OSRAM

STANDARD WORK
Loading and Unloading Aging Operator
Line B1-B2

Job Area	Job Description	Number Of Operator			Remarks
		Shift 1	Shift 2	Shift 3	
Aging	Loading / unloading lampu	1	1	1	3
	- Check Visual Lampu				Working for Aging Machine
Packing Lampu					
House Keeping					
	Loading lampu ke shrinkpack				
	Loading lampu				
	- Check Visual Lampu				
Packing Lampu					
House Keeping					
	Loading lampu ke shrinkpack				
	Loading lampu				
	- Check Visual Lampu				
Packing Lampu					
House Keeping					



Remark:
A. Tempat Karton Bekas
B. Tempat Powder Coating
C. Mixer Tabung Coating
D. Palet Tempat Material Bulb
E. Getter
F. Zincium
G. Roll mixer getter
H. Lemari mounting
I. Material Karton dan Dose
J. Palet Packing Lamp
K. Shrinkpack
L. Manual Solder




OSRAM

STANDARD WORK

Manual Solder Operator

Line B1-B2

STANDARD WORK						
Manual Solder Operator						
Line B1-B2						
Job Area	Job Description		Number Of Operator		Remarks	
	Shift 1	Shift 2	Shift 3	Sum		
Manual Solder	Manual solder (every PC lamp)	1	1	1	3	Working for Manual Solder and Basing Machine
	- Ambil lampu unsolder					
House Keeping						
Loading unfinish						
Ambil lampu uncut wire						
	- Check dan rework uncut wire					
Ambil lampu unsolder						
Menyambung						
Manual solder (every PC lamp)						
	- Ambil lampu unsolder					
House Keeping						




Biomass:



OSRAM

STANDARD WORK
Packing Operator
Line B1-B2

Job Area	Job Description	Number Of Operator				Remarks
		Shift 1	Shift 2	Shift 3	Sum	
Packing	Packing Lampu	1	1	1	3	Working for area Packing, Shrinkpack, Palet Pack, Material Karton, Aging Machine
	Menyiapkan Dosee					
	House Keeping					
	Loading lampu ke shrinkpack					
	Buat karton box					
	Menyiapkan plastik shrinkpack					
	Loading/ susun karton ke palet					
	Pasang barcode dan stiker					
	Packing Lampu					
	Menyiapkan Dosee					
	House Keeping					
	Loading lampu ke shrinkpack					



Remark :

- A. Tempat Karton Bekas
- B. Tempat Powder Coating
- C. Mixer Tabung Coating
- D. Palet tempat Material Bulb
- E. Getter
- F. Zirconium
- G. Roll mixer getter
- H. Lemari mounting
- I. Material Karton dan Dose
- J. Palet Packing Lamp
- K. Shrinkpack
- L. Manual Solder