




FORM SAFETY	Rev. No :	Form No. : SP05-SHE-F03
DAILY SAFETY PATROL	Effective Date :	Page No. : 1

Project : MRT
 Dept. : SHE
 Work item : D04 WORKSHOP

No.	FINDING	Finished	No.	FINDING
1			2	
		PIC		
	comment : Piles of pipe. Hazard Potential : Stumble, fall accidentally	SHE		Comment : Stucked wood pile. Hazard Potential : Stumble, Stuck
	Suggestion : Must be use signboard			Suggestion : Must be use signboard or clean the area
No.	FINDING	Finished	No.	FINDING
3			4	
		PIC		
	Comment : unclean condition.			Comment : Floors are not flat with puddles and many steel. Hazard Potential : fall a
	Suggestion : Clean the area or must be use signboard			Suggestion : gives bridge to access, clean the area and must use signboard



DATE

Finished



PIC

SHE

Finished

PIC





accidentally, stumble






FORM SAFETY	Rev. No :	Form No. : SP05-SHE-F03
DAILY SAFETY PATROL	Effective Date :	Page No. : 1

Project : MRT
 Dept. :
 Work item :

No.	FINDING	Finished	No.	FINDING
5		PIC	6	
		SHE		
<p>Comment : Spotlight cable. Hazard Potential :</p> <p>Suggestion : must use signboard</p>			<p>Comment : Unsafe Condition of power cord. Hazard Potential : short circuit, fire</p> <p>Suggestion : Replace the power cord and must use signboard</p>	
No.	FINDING	Finished	No.	FINDING
7		PIC	8	
<p>Comment : Unsafe Condition of equipment cable. Hazard Potential : Stumble, Short circuit, fire</p> <p>Suggestion : Improve cable position to be safe condition</p>			<p>Hazard Potential : Noise and dust.</p> <p>Suggestion : Worker use PPE (respirator and ear muff)</p>	



DATE

Finished

PIC

SHE

--

--

Finished

--

PIC

--

--

--

--

--

--

--

