

DAFTAR GAMBAR

Gambar 2.1 Pilar TPM	II-8
Gambar 3.1 <i>Flowchart</i> Tahap Penelitian	II-8
Gambar 4.1 Logo PT. Kati Kartika Murni Tangerang	IV-1
Gambar 4.2 Halaman Depan Pabrik	IV-1
Gambar 4.3 Tata Letak PT. Kati Kartika Murni	IV-5
Gambar 4.4 <i>Corrugator Manchine</i>	IV-8
Gambar 4.5 Mesin <i>Boiler</i>	IV-9
Gambar 4.9 <i>Glue Making Manchine</i>	IV-11
Gambar 4.10 <i>Double Becker</i>	IV-12
Gambar 4.11 NC Sliter	IV-13
Gambar 4.12 NC Sliter	IV-13
Gambar 4.13 OPC <i>Carton Sheet</i>	IV-14
Gambar 4.14 <i>Flowchart Carton Sheet</i>	IV-15
Gambar 4.15 Nilai Standar OEE	IV-24
Gambar 4.16 <i>Availability Ratio</i>	IV-25
Gambar 4.17 <i>Performance Ratio</i>	IV-26
Gambar 4.18 <i>Quality Ratio</i>	IV-28
Gambar 4.19 <i>Overall Equipment Effectiveness</i>	IV-29
Gambar 4.20 <i>Pareto Chart Downtime Mesin Corugator Bulan</i> Februari 2018	IV-32
Gambar 4.21 <i>Pareto Chart Jenis Kertas Putus Bulan Februari 2018</i>	IV-34

Gambar 4.22 Diagram <i>Fishbone C flute</i>	IV-35
Gambar 4.23 Diagram <i>Fishbone Kertas Putus B Flute</i>	IV-40
Gambar 4.24 <i>Pareto Chart Breakdown Mesin Corrugator Bulan Marct</i>	IV-48
Gambar 4.25 <i>Pareto Chart Breakdown Mesin Corrugator Bulan Maret</i>	IV-48
Gambar 4.26 Diagram <i>Fishbone Breakdown Timing Belt Pada Mesin Corrugator</i>	IV-49
Gambar 4.27 Diagram <i>Fishbone Breakdown Computer Sliter</i>	IV-54